
City of Baltimore Wet Smoke and Dyed	Page 1 of 1	
Sewershed: Gwynns Falls	Company: Savin	Date: 7/8/2009
Test to be performed: Smoke Dyed Water X	Ground Condition: Dry ✓ Damp ☐ Wet ☐	Supervisor: <u>JAW</u>
Manhole_ID: S03YY_015MH	Test ID: <u>D1032-026027</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S03YY_015MH
0			Water Level	
22.10000038	10		Tap Factory	From 4008 Liberty Heights
22.20000076			Dye Test Visible	@ TF - downspout
22.20000076			End of Survey	DYE TEST COMPLETED
22.20000076			Manhole	S05YY_008MH